HOT WORK PERMIT

All temporary operations involving open flames or producing heat and/or sparks require a Hot Work Permit. This includes, but is not limited to, Brazing, Cutting, Grinding, Soldering, Thawing, and Welding.

Name:	Wayne F	oster	Date Submitted:	1/13/2020 7:19:42 AM
Organiza	ation:	P1 Group		
Location:		CHILLER BUILDING #1		
PPMR #:				
Work Or	der #:			
Work Summary: Demo piping				
Work De	escription	: Cut grind Weld piping		
Precauti	ons Takeı	n:		
☐ Spi	Sprinklers and hose streams in service/operable.			
☑ Ho	Hot Work Equipment in good condition (e.g., power source, welding leads, torches, etc.)			
☑ Mu	Multi-purpose fire extinguisher and/or water pump can.			
REQUIR	EMENTS \	WITHIN 35 FEET OF WORK		
☑ Du	Dust, Lint, Debris, Flammable Liquids and oily deposits removed; floors swept clean.			
□ Ex	Explosive atmosphere in area eliminated.			
☐ Co	Combustible floors (e.g., wood, tile, carpeting) wet down, covered with damp sand or fire blankets.			
☑ Re	Remove flammable and combustible material where possible. Otherwise protect with fire blankets, guards, or metal shields.			
□ All	All wall and floor openings covered.			
☑ W	1 Walkways protected beneath hot work.			
WORK ON WALLS OR CEILINGS				
	Combustibles moved away from other side of wall.			
WORK IN CONFINED SPACES				
□ Со	nfined spa	ace cleaned of all combustibles (examp	le: grease, oil, flammable va	pors).
☐ Co	Containers purged of flammable liquids/vapors.			
☐ Fo	Follow confined space guidelines.			
FIRE WA	TCH/HO	T WORK AREA MONITORING		
☑ Fire	e watch wi	ill be provided during and for 30 minut	tes after work, including any	coffee or lunch breaks.
	Fire watch is supplied with an extinguisher, and/or water pump can, also making use of other extinguishers located throughout work area.			
☑ Fire	Fire watch is trained in use of this equipment and familiar with location of sounding alarm.			
☐ Fire	Fire watch may be required for opposite side of walls, above, and below floors and ceilings.			
OTHER PRECAUTIONS TAKEN				

☑ By checking this box, you certify that the above location has been examined, the precautions checked on the Hot Work Checklist have been taken to prevent fire, and by that acceptance, permission is authorized for this work by the University of Kansas.